

Grand Staircase-Escalante National Monument Road Report

Monday, June 10, 2019

All road conditions can change **RAPIDLY** due to weather.
Please contact the nearest visitor center for the most current conditions.

Roads to the East

Name	Date	Road	Comments
Burr Trail	6/7/2019	2WD	Conditions unknown for unpaved section! Per Capitol Reef NPS report!
Notom-Bullfrog	6/7/2019	2WD	Road is in good condition! Per Capitol Reef NPS Report!
Road to Bullfrog Marina	6/7/2019	2WD High Clearance	2WD High Clearance recommended for Bullfrog crossing. Per Capitol Reef NPS report!
Wolverine Loop	5/12/2019	2WD High Clearance	Ruts, High clearance recommended
Cedar Wash	6/7/2019	2WD	Road is in good condition a few rough and sandy spots.
Hole in the Rock	6/6/2019	2WD High Clearance	Road is good but dusty to Dry Fork then it gets very washboarded and rough. Recommend HC-4WD for last 7 miles.
Spencer Flat	5/19/2019	2WD High Clearance	Small ruts, gravel

Roads to the North

Name	Date	Road	Comments
Hells Backbone	6/7/2019	2WD High Clearance	Dry! Areas of washboards!
Posey Lake to Loa	6/10/2019	Impassable	Areas of SNOW! Passable to Davis Flat!
Whites Flat (FR #152)	6/10/2019	2WD High Clearance	Passable! Watch for rocks on the road! Can drive around them.
Griffin Top	6/10/2019	Impassable	CLOSED Snow
North Creek (FR #149)	6/10/2019	2WD High Clearance	Passable to campground! Unknown conditions to lakes!
Main Canyon	6/10/2019	2WD High Clearance	Passable to Widstoe!

Roads to the Central Areas

Name	Date	Condition	Comments
Smoky Mountain - Alvey Wash	5/27/2019	2WD	Rutted.
Left Hand Collet	4/13/2019	4WD	4WD required! Caution when driving!
Croton	5/27/2019	2WD	Road recently graded from Smoky Mt. jct. to Grand Bench jct.
Smoky Hollow	3/26/2019	2WD High Clearance	Rough at some wash crossings.

Roads to the West

Name	Date	Road	Comments
Cottonwood	6/8/2019	2WD High Clearance	Dry with a few rough areas and cross-ruts.
Skutumpah	6/9/2019	2WD	ROAD CLOSED 20 miles from South end. Dry and most has been recently graded to at least Lick Wash TH, possibly further.
Glendale Bench	6/7/2019	2WD High Clearance	Dry! Areas of washboards!
Paria Movie Set	6/1/2019	2WD High Clearance	Dry with shallow-moderate drops in washes past Day-use area.
House Rock Valley	6/5/2019	2WD High Clearance	Road in good condition; recently graded.
White House	6/10/2019	2WD High Clearance	Road in good condition.

