

Grand Staircase-Escalante National Monument Road Report

Thursday, August 22, 2019

All road conditions can **change RAPIDLY** due to weather.
Please contact the nearest visitor center for the most current conditions.

Roads to the East

Name	Date	Road	Comments
Burr Trail	8/16/2019	2WD	Dry
Notom-Bullfrog	8/18/2019	2WD	2WD a few rough spots. Per Capitol Reef NPS report.
Road to Bullfrog Marina	8/18/2019	2WD	2WD some rough spots. Per Capitol Reef NPS report!
Wolverine Loop	8/16/2019	2WD High Clearance	Dry, rough in places
Cedar Wash	6/7/2019	2WD	Road is in good condition a few rough and sandy spots.
Hole in the Rock	8/11/2019	2WD High Clearance, 4WD	Washboard; rocky south of Dance Hall Rock Recommend HC-4WD for last 7 miles.
Spencer Flat	8/18/2019	2WD High Clearance	Loose material, gravelly and rocky in places.

Roads to the North

Name	Date	Road	Comments
Hells Backbone	8/21/2019	2WD High Clearance	Rough spots and washboards! Conditions subject to change!
Posey Lake to Loa	8/21/2019	2WD High Clearance	Dry with rough spots and washboards! Conditions subject to change!
Whites Flat (FR #152)	8/21/2019	2WD High Clearance	Some rough spots! Conditions subject to change!
Griffin Top	8/21/2019	2WD High Clearance	Watch for Log Trucks! Conditions subject to change!
North Creek (FR #149)	8/21/2019	2WD High Clearance	Some rough spots! Conditions subject to change!
Main Canyon	8/21/2019	2WD	Dusty with areas of washboards! Conditions subject to change!

Roads to the Central Areas

Name	Date	Condition	Comments
Smoky Mountain - Alvey Wash	8/15/2019	2WD High Clearance	Some rough spots south of Croton jct.
Left Hand Collet	7/8/2019	4WD	4WD recommended! Caution when driving!
Croton	8/15/2019	2WD	2WD south of Alstrom Pt. jct. Unknown conditions north of there.
Smoky Hollow	7/17/2019	2WD High Clearance	Some wash crossings require high clearance.

Roads to the West

Name	Date	Road	Comments
Cottonwood	8/17/2019	2WD	Dry, Washboards, Recommend Moderate Clearance Vehicle.
Skutumpah	8/18/2019	2WD	From the South end; dry, washboards. Road Closed and impassable 20 miles from the South end.
Glendale Bench	8/21/2019	2WD	Good condition with a few washboards!
Paria Movie Set	8/11/2019	2WD	Dry. Washboards. Recommend Moderate Vehicle Clearance and 4WD after rain.
House Rock Valley	8/21/2019	2WD	Dry and dusty with areas of washboards!
White House	8/21/2019	2WD High Clearance	Washboards and rough areas. Clearance needed for crossing before campground.